

# Ph Meter

Memorial University Technical Services

Document No: TS-0104

Revision 1.0

18-Apr-2017

UEI Test Instruments

## 1.0 Equipment

The following is required:

Ph Meter

Certified Ph simulator

## 2.0 Procedure

Step 1: Obtain a digital Ph meter from a lab.

Step 2: Connect a certified meter to the Ph meter acquired in step 1. Select Ph levels of 4, 7 and 10.

Step 3: Record the values in the Ph Meter Calibration Sheet.

Step 4: Connect the meter being tested to the Ph meter acquired in step 1. Select Ph levels of 4, 7 and 10.

Step 5: Record the values in the Ph Meter Calibration Sheet.