

# Stroboscope

Memorial University Technical Services

Document No: TS-0113

Revision: 1

October 14, 2021

## 1.0 Equipment

Omega Tachometer TSE-0205

## 2.0 Procedure

Step1: Press trigger on stroboscope to power on. Select frequencies as per Stroboscope calibration sheet.

Step2: Operate tachometer by pressing start button. Point laser at stroboscope to be tested.

Step 3: Record measured frequencies on Stroboscope calibration sheet