

Appendix

Variable Transformer

Memorial University Technical Services

Document No: TS-0107

Revision 1.0

22-Sept-17

Variac W10MT3A

Power Stat 3PN126

1.0 Equipment

The following is required :

Fluke 435 Power Analyzer

2.0 Procedure

- 1) Connect the power analyzer to the Variable Transformer
- 2) Select voltages from minimum to maximum voltage output and record them in the Variable Transformer Verification Table .