



FOLLOW-UP TOTAL VOLATILE ORGANIC COMPOUND SAMPLING SIR WILFRED GRENFELL COLLEGE CORNER BROOK, NL

Prepared for:

SIR WILFRED GRENFELL COLLEGE 1 UNIVERSITY DRIVE CORNER BROOK, NL A2H 6P9

ATTENTION: MR. DAVID STURGE

Prepared by: **Pinchin LeBlanc Environmental Limited** 74 Broadway, Suite 201 Corner Brook, NL, A2H 4C8

Telephone: (709) 639-1984

December 9, 2013

Pinchin LeBlanc Environmental Project: 07-03-00068

74 BROADWAY, SUITE 201, CORNER BROOK, NL, A2H 4C8 TEL: (709) 639-1984 FAX: (709) 639-1999 SAINT JOHN, NB • DARTMOUTH, NS • LABRADOR CITY, NL • ST. JOHN'S, NL

EXECUTIVE SUMMARY

Pinchin LeBlanc Environmental Limited (Pinchin) was retained by Mr. Steve Hynes of Sir Wilfred Grenfell College (SWGC) to conduct Total Volatile Organic Compounds (TVOC) sampling. The follow up assessment was conducted throughout the Arts & Science building of SWGC in Corner Brook, NL. Ms. Karla Coles and Ms. Julia King performed the assessment from November 20 - 28, 2013.

The follow-up assessment was conducted as a result of air quality concerns following the application of floor sealant in the gymnasium, which occurred approximately three weeks ago. The initial report titled "Total Volatile Organic Compound Sampling, Sir Wilfred Grenfell College, Corner Brook, NL" was issued November 14, 2013.

The HVAC unit has been turned off since the floor sealant application and three exhaust fans have been placed in the gymnasium exhausting to the exterior. The HVAC unit was turned on for a brief time on November 27, 2013 but turned back off on the same day due to odour complaints by the occupants in the area.

The TVOC readings collected throughout the Arts & Science Building during November 20-28, 2013 were all below the Health Canada suggested comfort level of 0.4 ppm.

TABLE OF CONTENTS

1.0	INTRODUCTION AND SCOPE	.1
1.1	Statement of Understanding	.1
1.2	Scope of Work	.1
1.3	Assessment Methodology	. 1
1.4	Test Methods	. 1
2.0	ASSESSMENT AND FINDINGS	.2
2.1	Facility Description	.2
2.1.	1 Results of Interview	.2
2.2	Results of Indoor Air Quality Monitoring	.2
2.2.	1 Background	.2
2.2.2	2 Summary of Data	.3
	2.2.3.3 Conclusions and Recommendations	.5
3.0	LIMITATIONS	.5

1.0 INTRODUCTION AND SCOPE

1.1 Statement of Understanding

Pinchin LeBlanc Environmental Limited (Pinchin) was retained by Mr. Steve Hynes of Sir Wilfred Grenfell College (SWGC) to conduct Total Volatile Organic Compounds (TVOC) sampling. The follow up assessment was conducted throughout the Arts & Science building of SWGC in Corner Brook, NL. Ms. Karla Coles and Ms. Julia King performed the assessment from November 20 - 28, 2013.

The follow-up assessment was conducted as a result of air quality concerns following the application of floor sealant in the gymnasium, which occurred approximately three weeks ago. The initial report titled "Total Volatile Organic Compound Sampling, Sir Wilfred Grenfell College, Corner Brook, NL" was issued November 14, 2013.

1.2 Scope of Work

This follow up assessment was conducted throughout the Arts & Science building of SWGC and involved the following activities:

- Development of a sampling strategy;
- Measurement of the following indoor air quality (IAQ) factors:
 - Concentration of total volatile organic compounds (TVOC); and,
- Preparation of this report.

1.3 Assessment Methodology

The investigator interviewed the SWGC representative to discuss the sampling strategy. It was reported that since the sealant was applied to the gymnasium floor, there are still concerns with the smell migrating to other areas of the building. It was decided that the sampling would begin in the area of the gymnasium and expand to the surrounding areas and second floor adjacent to the gymnasium.

1.4 Test Methods

Spot-check sampling for total volatile organic compounds (TVOCs) was conducted with a miniRAE. The instrument is a portable gas detector that uses Photo-ionization technology to detect a large range of Volatile Organic Compounds (VOCs). Outdoor ambient air measurements were made in addition to samples collected in the building.

All sampling was performed in compliance with current professional practice^{1.}

2.0 ASSESSMENT AND FINDINGS

2.1 Facility Description

The Arts & Science building is a three storey structure with basement. The gymnasium is located in the southwest corner of the building.

2.1.1 Results of Interview

The following information was reported to the consultant by the SWGC representative:

• The HVAC unit has been turned off since the floor sealant application and three exhaust fans have been placed in the gymnasium exhausting to the exterior. The HVAC unit was turned on for a brief time on November 27, 2013 but turned back off, the same day, due to odour complaints by the occupants in the area.

2.2 Results of Indoor Air Quality Monitoring

2.2.1 Background

The term "volatile organic compounds" (VOCs) refers to organic compounds with a boiling point of greater than 50°C and less than 260°C. Offices or other non-industrial workplaces can contain many VOC sources such as paints, furniture, cleaners, personal care products and office equipment. Where VOCs are present at higher concentrations, there is a risk of adverse health effects such as unacceptable odours, eye, nose or throat irritation, or headache. Indoor air in office environments is usually a mixture of many VOCs present in varying concentrations, measured in micrograms per cubic metre (μ g/m³) or parts per million in air (ppm). The sum of the VOCs in an environment is termed the Total Volatile Organic Compound concentration (TVOC), frequently measured by direct reading instrumentation or laboratory methods. IAQ investigators use the TVOC concentration to estimate the risk of adverse health effects.

There is no legislated TVOC standard or even a consensus standard set to prevent all IAQ complaints from VOCs in office buildings. In the past, Health Canada published guidance based on work by the Danish researcher Lars Molhave, recommending a threshold of $200 \,\mu g/m^3$ for no adverse health effects, and noting that discomfort could be expected above 3,000 $\mu g/m^3$. However, Molhave has recently withdrawn support for these thresholds and Pinchin no longer recommends use of the Health Canada TVOC guidelines.

¹ American Industrial Hygiene Association: Field Guide for the Determination of Biological Contaminants in Environmental Samples. H.K. Dillon, P.A. Heinsohn, and J.D. Miller, Eds. AIHA, Fairfax, VA (1996).

The literature does include some guidance on typical and maximum acceptable concentrations. The US Environmental Protection Agency (US EPA) has conducted one of the largest IAQ investigations of IAQ in office buildings, including VOC concentrations. In the period of 1994-1998, the US EPA Building Assessment Survey and Evaluation (BASE) study surveyed 100 randomly selected office buildings across 37 cities and 25 states. These were not known to be "problem" buildings. The study found 25 VOC compounds to be present in every building tested. This study found TVOC levels in the 100 randomly selected office buildings to be about 400 μ g/m³, while some buildings ranged as high as 1,200 μ g/m³. Under the Canada Green Building Council Leadership in Energy and Environmental Design (LEED) program, newly built buildings receive IAQ credits for having TVOC concentrations up to 1,000 μ g/m³ (0.4 ppm) to be at little risk of IAQ complaints. Complaints might be expected if concentrations were much above that level.

2.2.2 Summary of Data

The spot check measurements throughout the Arts & Science building are provided in table 2.2.2 presented below. It should be noted that all sampling results were instantaneous and recommendations provided to SWGC in real time while data was being collected.

Location	TVOC (ppm)			
November 20, 2013				
Outdoors	0.0			
Pool Viewing Area	0.0			
Help Desk	0.0			
Stage Craft	0.0			
C & C	0.0			
Props	0.0			
Gym Hallway	0.0			
Gym	0.0			
November 21, 2013				
Outdoors	0.0			
Pool Viewing Area	0.0			
Help Desk	0.0			
Stage Craft	0.0			
Wardrobe	0.0			
Props	0.0			

Spot Check Monitoring of TVOCs Arts & Science Building, SWGC, Corner Brook, NL November 20-28, 2013

Location	TVOC (ppm)			
Gym Hallway	0.0			
Stairwell	0.0			
Gym	0.0			
November 22, 2013				
Outdoors	0.0			
Pool Viewing Area	0.0			
Help Desk	0.0			
Stage Craft	0.0			
C & C	0.0			
Resource Centre	0.0			
Props	0.0			
Wardrobe	0.0			
Gym Hallway	0.0			
Gym	0.0			
Cage	0.0			
Gym Offices	0.0			
Novemb	ver 23, 2013			
Outdoors	0.0			
Pool Viewing Area	0.0			
Help Desk	0.0			
Stage Craft	0.0			
C & C	0.0			
Resource Centre	0.0			
Party Room	0.0			
Props	0.0			
Wardrobe	0.0			
Gym Hallway	0.0			
Gym	0.0			
November 25, 2013				
Outdoors	0.0			
Pool Viewing Area	0.0			
Help Desk	0.0			
Stage Craft	0.0			
C & C	0.0			
Resource Centre	0.0			
Party Room	0.0			
Props	0.0			
Wardrobe	0.0			
Gym Hallway	0.0			
Gym	0.0			

Location	TVOC (ppm)		
November 27, 2013			
Outdoors	0.0		
Gym Hallway	0.0		
Gym	0.0		
Pool Viewing Area	0.0		
Help Desk	0.0		
November 28, 2013			
Outdoors	0.0		
Gym Hallway	0.0		
Gym	0.0		
Pool Viewing Area	0.0		
Help Desk	0.0		
1. Total volatile organic compounds (TVOC) levels above 1.0 mg/m ³ (approximately 0.4 ppm), one may expect complaints.			
* Numbers in RED are above the recommended va	lue.		

2.2.3.3 Conclusions

The TVOC readings collected throughout the Arts & Science Building during November 20-28, 2013 were all below the Health Canada suggested comfort level of 0.4 ppm.

3.0 LIMITATIONS

Work performed by Pinchin was conducted in accordance with generally accepted engineering or scientific practices current in this geographical area at the time the work was performed. No warranty is either expressed or implied, or intended by the agreement executed with the Client, or by furnishing oral or written reports or findings. The Client acknowledges that subsurface and concealed conditions may vary from those encountered or inspected. Pinchin could only comment on the conditions observed on the date(s) the assessment was performed.

Pinchin makes no other representations whatsoever, including those concerning the legal significance of its findings or as to other legal matters mentioned in this report, including, but not limited to, ownership of any property, or the application of any law to the facts set forth herein. With respect to regulatory compliance issues, regulatory statutes are subject to interpretation and these interpretations may change over time. Pinchin accepts no responsibility for consequential financial effects on transactions or property values, or requirements for follow-up actions and costs.

The liability of Pinchin or its staff will be limited to the lesser of the fees paid or actual damages incurred by the Client. Pinchin will not be responsible for any consequential or indirect damages. Pinchin will only be liable for damages resulting from negligence of Pinchin. All

claims by the Client shall be deemed relinquished if not made within two years after last date of services provided.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party other than the Client, unless the Client, in writing, requests information to be provided to a third party or unless disclosure by Pinchin is required by law. Any use by a third party, of reports or documents authored by Pinchin, or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted.

Air sampling results (if any) will apply only to the time and conditions of the testing and may not be used to reliably predict conditions on other days.

PINCHIN LEBLANC ENVIRONMENTAL LIMITED

Per...Julia King *Project Manager* IAQ Microbial Contamination <u>jking@pinchinleblanc.com</u>

torid Ming

Reviewed by: David Muise, OHST Senior Occupational Hygienist IAQ Microbial Contamination dmuise@pinchinleblanc.com