

Asbestos Building Survey Information

Room #	Bldg. System	Component	Material Type	Access	Conditions				Quantity	Sample No.	Sample Location	Sample Description	Result
					Good	Fair	Poor	Sprayed					
PS1V03			Door Caulking	A	X				--	PS-03		Interior Door Caulking	5% Chrysotile
PS1000			9" x 9" Vinyl Floor Tile	A	X				~160 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1000A			Pipe Fitting Insulation	A, B, C	X				4	PS-12	PS1000A	Grey Insulation	50% Chrysotile
PS1002			9" x 9" Vinyl Floor Tile	A	X				~1000 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1002A			9" x 9" Vinyl Floor Tile	A	X				~2200 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1V01			1' x 1' Vinyl Floor Tile	A	X				~ 80 ft ²	PS-11	PS1V01	Black with White, and Mastic	2% and 2% Chrysotile
PS1004			9" x 9" Vinyl Floor Tile	A	X				~700 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1005			9" x 9" Vinyl Floor Tile	A	X				~350 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1006			9" x 9" Vinyl Floor Tile	A	X				~450 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1007			9" x 9" Vinyl Floor Tile	A	X				~650 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1007B			9" x 9" Vinyl Floor Tile	A	X				~100 ft ²	PS-07	PS1002	Teal with Blue and White, and Mastic	3% and 5% Chrysotile
PS1007B			1' x 1' Vinyl Floor Tile	A	X				~ 50 ft ²	PS-11	PS1V01	Black with White, and Mastic	2% and 2% Chrysotile
PS1007C			1' x 1' Vinyl Floor Tile	A	X				~ 130 ft ²	PS-11	PS1V01	Black with White, and Mastic	2% and 2% Chrysotile

No Access was available to the following rooms: PS-1008 (due to confidential information) and PS1000B (Server Room)

Access: A - Areas within reach from the floor. B - Frequently entered maintenance areas floor level. C - exposed / concealed above 8 ft, crawl space, etc. D - Inaccessible